




EXPLANATION
Quaternary deposits are more extensive
than shown because they were not mapped
where less than 3 feet thick



BEDROCK

Bedrock locally is greatly faulted and fractured
and steeply dipping. Certain combinations of
these conditions produce unstable slopes, which
are present at many places along the mountain
front



Horizontal Inclined Vertical Overturned
Strike and dip of beds

85
Strike and dip of joints